

| SL No | Inward No       | Testing Date<br>Report Date    | Client Name and<br>Address                                                                                                      | Agency Name and<br>Address                                                                      | Material<br>Test    | Project.  |
|-------|-----------------|--------------------------------|---------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|---------------------|-----------|
| 01    | 1001<br>2022-23 | TD-21/11/2022<br>RD-2/12/2022  | BBMP Office of Executive<br>Engineer, No. 2152/20,<br>Bytrayanapura Division<br>Defence Colony, Shaker Nagar<br>Bangalore - 92  | Sri. Chidananda Murthy. R<br>No. 14, 2nd cross<br>Vinayaka layout,<br>Haramann, Bangalore - 43  | Steel               | Package-4 |
| 02    | 1002<br>2022-23 | TD-21/11/2022<br>RD-3/12/2022  | BBMP Office of Executive<br>Engineer, No. 2152/20,<br>Bytrayanapura Division,<br>Defence Colony, Shaker Nagar<br>Bangalore - 92 | Sri. Chidananda Murthy. R<br>No. 16, 2nd cross,<br>Vinayaka layout,<br>Haramann, Bangalore - 43 | Coarse<br>Aggregate | Package-4 |
| 03    | 1003<br>2022-23 | TD-21/11/2022<br>RD-14/12/2022 | BBMP Office of Executive<br>Engineer, No. 2152/20<br>Bytrayanapura Division<br>Defence Colony, Shaker Nagar,<br>Bangalore - 92  | Sri. Chidananda Murthy. R<br>No. 16, 2nd cross<br>Vinayaka layout<br>Haramann, Bangalore - 43   | Fine<br>Aggregate   | Package-4 |
| 04    | 1004<br>2022-23 | TD-22/11/2022<br>RD-22/12/2022 | BBMP Office of Executive<br>Engineer, No. 2152/20<br>Bytrayanapura Division,<br>Defence Colony, Shaker Nagar,<br>Bangalore - 92 | Sri. Chidananda Murthy. R<br>No. 16, 2nd cross<br>Vinayaka layout<br>Haramann, Bangalore - 43   | Cement              | Package-4 |
| 05    | 1005<br>2022-23 | TD-4/1/2023<br>RD-6/1/2023     | BBMP Office of Executive<br>Engineer, No. 2152/20,<br>Bytrayanapura Division<br>Defence Colony, Shaker Nagar,                   | Sri. Chidananda Murthy. R<br>No. 16, 2nd cross<br>Vinayaka layout<br>Haramann, Bangalore - 43   | BC                  | Package-4 |

| Sl No. | Inward No.      | Testing Date<br>Report Date                                                             | Client Name and<br>Address                                                                                                      | Agency Name and<br>Address                                                           | Material<br>Test | Project     |
|--------|-----------------|-----------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|------------------|-------------|
| 06     | 1006<br>2022-23 | T.D -<br>R.D - 6/11/2023                                                                | BBMP Office of Executive<br>Engineer, No. 2152/20,<br>Byrayeranayana Division<br>Defence Colony, Shakti Nagar<br>Bangalore - 92 | Sri. Chidananda Murthy . R<br>No. 16, 2nd cross<br>Vinyaga layout.<br>Bangalore - 43 | Cubes            | Package - 4 |
| 07     | 1007<br>2022-23 | T.D - 18/1/23<br>R.D - 23/1/23                                                          | BBMP Office of Executive<br>Engineer, No. 2152/20,<br>Byrayeranayana Division<br>Defence Colony, Shakti Nagar<br>Bangalore - 92 | Sri. Chidananda Murthy . R<br>No. 16, 2nd cross<br>Vinyaga layout<br>Bangalore - 43  | WMM              | Package - 4 |
| 08     | 1008<br>2022-23 | T.D - 31/1/23<br>31/2/23<br>R.D - 23/2/23                                               | BBMP Office of Executive<br>Engineer, No. 2152/20,<br>Byrayeranayana Division<br>Defence Colony, Shakti Nagar<br>Bangalore - 92 | Sri. Chidananda Murthy . R<br>No. 16, 2nd cross<br>Vinyaga layout<br>Bangalore - 43  | BC               | Package - 4 |
| 09     | 1010<br>2022-23 | T.D - 6/2/2023<br>8/2/2023<br>13/2/2023<br>15/2/23, 16/2/23<br>19/2/23<br>R.D - 23/2/23 | BBMP Office of Executive<br>Engineer, No. 2152/20,<br>Byrayeranayana Division<br>Defence Colony, Shakti Nagar<br>Bangalore - 92 | Sri. Chidananda Murthy . R<br>No. 16, 2nd cross<br>Vinyaga layout<br>Bangalore - 43  | DBM              | Package - 4 |
| 10     | 1016<br>2022-23 | T.D - 7/2/23<br>9/2/23, 14/2/23<br>16/2/23, 20/2/23<br>26/2/23<br>R.D - 23/2/23         | BBMP Office of Executive<br>Engineer, No. 2152/20,<br>Byrayeranayana Division<br>Defence Colony, Shakti Nagar<br>Bangalore - 92 | Sri. Chidananda Murthy . R<br>No. 16, 2nd cross<br>Vinyaga layout<br>Bangalore - 43  | BC               | Package - 4 |

| SL No | Inward No.       | Testing Date Report Date                                                             | Client Name and Address                                                                                            | Agency Name and Address                                                            | Material Test | Project   |
|-------|------------------|--------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|---------------|-----------|
| 11    | 1022<br>2022-23  | TD -<br>RD-27/1/2023                                                                 | BBMP Office of Executive Engineer, No. 2152/20, Bytayanapura Division, Defence Colony, Shaker Nagar Bangalore - 92 | Sri. Chidananda Murthy. R<br>No. 16, 2nd cross<br>Vingala layout<br>Bangalore - 43 | Cubes         | Package-4 |
| 12    | 1023<br>2023-24  | TD - 3/3/2023<br>15/3/2023<br>18/3/2023<br>RD - 23/2/23                              | BBMP Office of Executive Engineer, No. 2152/20, Bytayanapura Division, Defence Colony, Shaker Nagar Bangalore - 92 | Sri. Chidananda Murthy. R<br>No. 16, 2nd cross<br>Vingala layout<br>Bangalore - 43 | BC            | Package-4 |
| 13    | 1026<br>2023-24  | TD - 25/3/2023<br>27/3/2023<br>28/3/2023<br>29/3/2023<br>30/3/2023<br>RD - 03/4/2023 | BBMP Office of Executive Engineer, No. 2152/20, Bytayanapura Division, Defence Colony, Shaker Nagar Bangalore - 92 | Sri. Chidananda Murthy. R<br>No. 16, 2nd cross<br>Vingala layout<br>Bangalore - 43 | BC            | Package-4 |
| 14    | 1031<br>2023-24  | TD - 3/5/2023<br>RD - 5/5/2023                                                       | BBMP Office of Executive Engineer, No. 2152/20, Bytayanapura Division, Defence Colony, Shaker Nagar Bangalore - 92 | Sri. Chidananda Murthy. R<br>No. 16, 2nd cross<br>Vingala layout<br>Bangalore - 43 | BC            | Package-4 |
| 15    | 1032-<br>2023-24 | TD - 3/6/2023<br>5/6/2023<br>RD - 8/6/2023                                           | BBMP Office of Executive Engineer, No. 2152/20, Bytayanapura Division, Defence Colony, Shaker Nagar Bangalore - 92 | Sri. Chidananda Murthy. R<br>No. 16, 2nd cross<br>Vingala layout<br>Bangalore - 43 | BC            | Package-4 |

| Sl No | Inward No.      | Test Date<br>Report Date                  | Client Name and<br>Address                                                                                                        | Agency Name and<br>Address                                                          | Material<br>Test | Project   |
|-------|-----------------|-------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------|-----------|
| 16    | 1034<br>2023-24 | TD-3/7/2023<br>RD-6/7/2023                | BBMP Office of Executive<br>Engineer, No. 215/21/20<br>Bytayanapura Division<br>Defence Colony, Shaker Nagar<br>Bangalore - 92    | Sri. Chidananda Murthy. R<br>No. 16, 2nd Cross<br>Vinyaka layout<br>Bangalore - 43  | BC               | Package-4 |
| 17    | 1035<br>2023-24 | TD-14/7/2023<br>RD-17/7/23                | BBMP Office of Executive<br>Engineer, No. 215/21/20<br>Bytayanapura Division<br>Defence Colony, Shaker Nagar<br>Bangalore - 92    | Sri. Chidananda Murthy. R<br>No. 16, 2nd Cross<br>Vinyaka layout<br>Bangalore - 43  | BC               | Package-4 |
| 18    | 1036<br>2023-24 | TD-3/10/2023<br>RD-6/10/2023              | BBMP Office of Executive<br>Engineer, No. 215/21/20<br>Bytayanapura Division<br>Defence Colony, Shaker Nagar<br>Bangalore - 92    | Sri. Chidananda Murthy. R<br>No. 16, 2nd Cross<br>Vinyaka layout<br>Bangalore - 43  | BC               | Package-4 |
| 19    | 1037<br>2023-24 | TD-3/11/2023<br>4/11/2023<br>RD-6/11/2023 | BBMP Office of Executive<br>Engineer, No. 215/21/20,<br>Bytayanapura Division,<br>Defence Colony, Shaker Nagar,<br>Bangalore - 92 | Sri. Chidananda Murthy. R<br>No. 16, 2nd Cross,<br>Vinyaka layout<br>Bangalore - 43 | BC               | Package-4 |
| 20    | 1039<br>2023-24 | TD-14/11/2023<br>RD-16/11/2023            | BBMP Office of Executive<br>Engineer, No. 215/21/20,<br>Bytayanapura Division,<br>Defence Colony, Shaker Nagar<br>Bangalore - 92  | Sri. Chidananda Murthy. R<br>No. 16, 2nd Cross<br>Vinyaka layout<br>Bangalore - 43  | BC               | Package-4 |